

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022051**Date Inspected:** 12-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr.Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

BAY # 14

ULTRASONIC TESTING

ZPMC NWIT No: 08525

This QA Inspector performed Ultrasonic Testing (UT) of approximately 10% of the length previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an (UT) report on this date. The members are identified as OBG 14East. The weld designations are as follows:

SEG3019E-1-182, 179, 178

This QA Inspector randomly observed the following work in progress.

OBG 14EAST

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066418 performing the Shielded Metal

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Arc Welding process on weld 039 located at PCMK SEG3019BB. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-Tc-u5b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 037997 performing the Shielded Metal Arc Welding process on weld 083 located at PCMK SEG3019BB. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-Tc-u5b-Fcm-1

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 070006 performing the Shielded Metal Arc Welding process on weld 100 located at PCMK SEG3019AW. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066163 performing the Shielded Metal Arc Welding process on weld 105 located at PCMK SEG3019AW. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066236 performing the Flux Cored Arc Welding process on weld 264 located at PCMK SEG3019E-2. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066763 performing the Flux Cored Arc Welding process on weld 042 located at PCMK SEG3019Z. ZPMC QC Mr. Zhu Yuan Yuan was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2231-ESAB.

This QA Inspector observed installation /mounting of bearing block in progress at AP3031.

This Quality Assurance (QA) Inspector observed ZPMC personnel performing heat straightening, member identified as Anchor plate AP3004. Distortion appeared to be caused by welding. Weld number identified as SEG3019X-004~009. ZPMC Quality Control (QC) inspector identified as Mr. Zhong Guo Hui was present to monitor the heat straightening process. The heat straightening appeared to comply with heat straightening Report HSR1 (B)-10173.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By: Utekar,Shrikant

Quality Assurance Inspector

Reviewed By: Patterson,Rodney

QA Reviewer